

Rajgurunagar Municipal Council had installed two systems of E&P Community Farm Company in Bhaji Mandi, after which we inspected the system as per their claim, all the claims failed.

Problem:-

1. The weight of the waste dumped into the system was not being received.
2. The material attached to the system was missing because it was not fitted properly.
3. There is no automatic facility to take out the internal waste after filling the system.

Suggestion:-

The system developed at Vigyan Ashram is suitable for BSF in Waste Management.